

VCDS

Windows Based VAG/VAS Emulator Running on Windows 10 x64
VCDS Version: Release 20.12.0 Data version: 20201124 DS322.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000 000000

Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF
Mileage: 232788km-144647mi Repair Order:

Chassis Type: 4G-AU57 (4G0)
Scan: 01 02 03 05 08 09 10 15 16 17 19 28 36 3B 42 44 46 52 53 55
56 5F 62 6D 72 8F 90

VIN: WAUZZZ4G7BN023481 Mileage: 232788km-144647miles

01-Engine -- Status: OK 0000
02-Auto Trans -- Status: Malfunction 0010
03-ABS Brakes -- Status: OK 0000
04-Steering Angle -- Status: OK 0000
05-Acc/Start Auth. -- Status: OK 0000
08-Auto HVAC -- Status: Malfunction 0010
09-Cent. Elect. -- Status: OK 0000
10-Park/Steer Assist -- Status: OK 0000
15-Airbags -- Status: OK 0000
16-Steering wheel -- Status: OK 0000
17-Instruments -- Status: OK 0000
19-CAN Gateway -- Status: OK 0000
28-HVAC, Rear -- Status: Malfunction 0010
36-Seat Mem. Drvr -- Status: OK 0000
3B-Sensor Elect. -- Status: OK 0000
42-Door Elect, Driver -- Status: OK 0000
44-Steering Assist -- Status: Malfunction 0010
46-Central Conv. -- Status: OK 0000
52-Door Elect, Pass. -- Status: OK 0000
53-Parking Brake -- Status: OK 0000
55-Headlight Range -- Status: OK 0000
56-Radio -- Status: Malfunction 0010
5F-Information Electr. -- Status: Malfunction 0010
62-Door, Rear Left -- Status: OK 0000
6D-Trunk Elect. -- Status: OK 0000
72-Door, Rear Right -- Status: OK 0000
8F-Pretens. Frt Left -- Status: OK 0000
90-Pretens. Frt Right -- Status: OK 0000

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 2

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 01: Engine (J623-CDUC) Labels: 059-907-401-V2.clb
Part No SW: 4G0 907 401 F HW: 4G0 907 401
Component: 3.0TDI EDC17 H37 0003
Revision: 53H37---
Coding: 1A254012042601020000
Shop #: WSC 02311 785 00200
ASAM Dataset: EV_ECM30TDI0114G0907401F 001003
ROD: EV_ECM30TDI0114G0907401F.rod
VCID: 2649AB5A59E704B459-8072

No fault code found.
Readiness: 0 0 0 0 1

Address 02: Auto Trans (J217) Labels: 0B5-927-156.clb
Part No SW: 4G0 927 156 K HW: 0B5 927 156 F
Component: 0B5 30 TDIRdW H05 0010
Revision: --H05--- Serial number: 0000001759
Coding: 000001
Shop #: WSC 02311 785 00200
ASAM Dataset: EV_TCMDL501 A02087
ROD: EV_TCMDL501.rod
VCID: 346D41129F3B6624D7-8060

1 Fault Found:
7966 - Signal Line for Gear Display on Selector Lever
P1894 00 [038] - Implausible Signal
Intermittent - Not Confirmed - Tested Since Memory Clear
Freeze Frame:
Fault Status: 00000001
Fault Priority: 2
Fault Frequency: 3
Reset counter: 40
Mileage: 232788 km
Date: 2023.12.10
Time: 14:13:01

Engine RPM: 819 /min
Transmission input speed: 819 /min
Transmission output speed: 0 /min
Engine torque: -24 Nm
ATF temperature: 31 °C
Accelerator pedal position: 0.0 %
Clutch status: Beide Kupplungen offen

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 3

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 03: ABS Brakes (J104) Labels: 4G0-907-379-V1.clb
Part No SW: 4G0 907 379 HW: 4G0 907 379
Component: ESP PREMIUM H08 0190
Revision: ----- Serial number: -----
Coding: 27A68702E465E140DB00
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_ESPPremiAU57X 003013
ROD: EV_ESPPremiAU57X_003.rod
VCID: 6ED9937AB1970CF4E1-803A

No fault code found.

Address 05: Acc/Start Auth. (J393) Labels: 8K0-907-064-05.clb
Part No SW: 4H0 907 064 AP HW: 4H0 907 064 AP
Component: BCM2 2.0 H24 0217
Revision: 00002001
Coding: 01AA3000000000000000
Shop #: WSC 02391 785 00200
VCID: 77F7B61EC6CD4D3C32-8022

Subsystem 2 - Part No SW: 4H0 905 852 B HW: 4H0 905 852 B
Component: J764 ELV MLB H38 0044
Serial number: 2311000064908013

No fault code found.

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 4

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 08: Auto HVAC (J255) Labels:| 4G0-820-043-4Z.clb
Part No SW: 4G0 820 043 K HW: 4G0 820 043 K
Component: KLIMA 4 ZONEN H11 0056
Serial number: 01041100040019
Coding: 3603007800
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_AirCondiComfoUDS_002029
ROD: EV_AirCondiComfoUDS_002.rod
VCID: 2757A65E5EED1DBC62-8072

2 Faults Found:

0092 - Motor for Right Center Vent Flap

B10CC 31 [009] - No Signal

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 3

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Date: 2023.12.10

Time: 14:12:53

Voltage terminal 30: 14.45 V

Outside temperature: 8.0 °C

Inside temperature: 20.87 °C

Right center vent motor-Act.val.: 0

Right center vent motor-Target value: 0

Right center vent motor-Stop open: 10843

Right center vent motor-Stop closed: 10000

0093 - Motor for Right Center Vent Flap

B10CC 29 [009] - Signal Implausible

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 3

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Date: 2023.12.10

Time: 14:12:52

Voltage terminal 30: 14.45 V

Outside temperature: 8.0 °C

Inside temperature: 20.86 °C

Right center vent motor-Act.val.: 0

Right center vent motor-Target value: 0

Right center vent motor-Stop open: 10843

Right center vent motor-Stop closed: 10000

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 5

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 09: Cent. Elect. (J519) Labels: 4H0-907-063-V1.clb
Part No SW: 4H0 907 063 N HW: 4H0 907 063 F
Component: BCM1 2.0 H12 0092
Revision: 20012002 Serial number: 00000001000472
Coding: 2600201040348FE081810083E0001D0CCF9CC30826090101000008602300
Shop #: WSC 02391 785 00200
VCID: 336F420E9235611CCE-8066

Subsystem 1 - Part No SW: 4G1 955 119 HW: 4G8 955 119 Labels: 1KX-955-119.CLB
Component: WWS57X 110329 H35 0051
Serial number: 110331134229
Coding: 0045F7

Subsystem 2 - Part No SW: 8K0 955 559 HW: 8K0 955 559 Labels: 8K0-955-559.CLB
Component: RLS H04 0003
Serial number: 11355515
Coding: 02562B

Subsystem 3 - Part No SW: 4G0 941 531 E HW: 4G0 941 531 E
Component: E1 - LDS H07 0044
Serial number: 24 03 2011 00000704

Subsystem 4 - Part No SW: 4H0 907 658 HW: 4H0 907 658
Component: AQ_Hum_Sensor H02 0002
Serial number: 5B280B9500000000000001

No fault code found.

Address 10: Park/Steer Assist (J446) Labels: 4H0-919-475-7X2.clb
Part No SW: 4H0 919 475 H HW: 4H0 919 475 C
Component: PARKHILFE ACC H07 0030
Revision: 11001001 Serial number: 55901106602372
Coding: 100303
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_EPHVA18AU57X0000 001002
ROD: EV_EPHVA18AU57X0000_001.rod
VCID: 3777761E8E4D8D3CF2-8062

No fault code found.

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 6

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 15: Airbags (J234) Labels: * 4H0-959-655.clb
Part No SW: 4H0 959 655 C HW: 4H0 959 655 C
Component: Airbag10.43 H40 0040
Revision: ----- Serial number: 003JG00207FJ
Coding: 30314530323130303035554A304C34473853
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_AirbaAU10BPAAU64X 001014
ROD: EV_AirbaAU10BPAAU64X_VW51.rod
VCID: 36697B1A89477434E9-8062

Crash sensor for side airbag: driver side:
Serial number: 3575HRB405V0CE32C8PJ

Front Passenger's Side Airbag Crash Sensor:
Serial number: 3585HRB40610CE328OO2

Rear Side Airbag Crash Sensor (on driver's side):
Serial number: 3515JRB40630G2I231HE

Passenger side rear thorax airbag crash sensor:
Serial number: 3525JRB40650G2I2B0CJ

Crash sensor for front airbag: driver side:
Serial number: 3554VRB40630FUO87P92

Crash sensor for front airbag: front passenger side:
Serial number: 3564VRB40630FUO8CGQG

No fault code found.

Address 16: Steering wheel (J527) Labels: . 4H0-953-568.clb
Part No SW: 4G0 953 568 A HW: 4G0 953 568 A
Component: Lenks.Modul H05 0201
Revision: 00000000 Serial number: 20110329000973
Coding: 000034
Shop #: WSC 02391 785 00200
VCID: 30654D0263235A04B3-8064

Subsystem 1 - Part No SW: 4G0 951 528 A HW: 4G0 951 528 A
Component: E221 - MFL H07 0009

No fault code found.

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 7

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 17: Instruments (J285) Labels:| 4H0-920-xxx-17.clb-SRI1
Part No SW: 4G8 920 930 P HW: 4G8 920 930 P
Component: TDieRdw H34 0312
Revision: 19100074 Serial number: 658140311593002
Coding: 03AF01020B030008020100
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_RBD4K 004033
ROD: EV_RBD4K_AU57.rod
VCID: 3A716F2ABD5F90540D-806E

No fault code found.

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 8

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 19: CAN Gateway (J533) Labels: * None
Part No SW: 4G0 907 468 C HW: 4G0 907 468 A
Component: J533--Gateway H08 0204
Revision: ----- Serial number: 00000000124012
Coding: 00CD077D00
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_GatewUDS 001025
ROD: EV_GatewUDS_AU57.rod
VCID: 30654D026B235A04B3-8064

Battery Monitoring Control Module:
Subsystem 1 - Part No SW: 8X0 915 181 HW: 8X0 915 181
Component: J367-BDM H07 0140
Serial number: 00000000005650736879

Voltage stabilizer:
Subsystem 2 - Part No SW: 8K0 959 663 HW: 8K0 959 663
Component: J532_DCDCStab H17 0042
Serial number: 11073000999021200181

1 Fault Found:

0264 - Powertrain Databus (VAG Single-Wire Mode) (SAE L Shorted H)

U0009 00 [008] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Intermittent - Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 3

Fault Frequency: 20

Reset counter: 131

Mileage: 232788 km

Date: 2023.12.10

Time: 14:13:39

Voltage terminal 30: 14.5 V

Voltage terminal 15: 14.5 V

Control Module temperature: 23 °C

System status: Terminal 15 on

IN ESP_standstill flag: standstill detected

Engine running: On

IN ZAS_Te_X: On

Terminal 15 status via CAN: On

Terminal 15 status: On

Datenfeld: 0

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 9

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 28: HVAC, Rear (E265) Labels: * 4G0-919-158.clb
Part No SW: 4G0 919 158 C HW: 4G0 919 158 C
Component: KLIMA FOND H07 0056
Serial number: 29031100040274
Coding: 00
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_ClimaContrUnitRearUDS 002012
ROD: EV_ClimaContrUnitRearUDS_002.rod
VCID: 2F674E7E761D45FCAA-807A

1 Fault Found:

0069 - Position Sensor in Rear Right Upper Body Vent
B10E6 11 [009] - Short to Ground
Confirmed - Tested Since Memory Clear
Freeze Frame:

Fault Status: 00000001
Fault Priority: 3
Fault Frequency: 1
Reset counter: 91
Mileage: 232788 km
Date: 2023.12.10
Time: 14:12:52

Voltage terminal 30: 14.66 V
Terminal 15 status: Terminal 15 on
Supply voltage for external components: 5.00 V

Address 36: Seat Mem. Drvr (J136) Labels: None
Part No SW: 4G8 959 760 HW: 4G8 959 760
Component: MEM-FS H03 0153
Revision: AA000000 Serial number: 00000006062057
Coding: 0058130000006001000001010101102030303232203232
Shop #: WSC 02311 785 00200
VCID: 77F7B61EC6CD4D3C32-8022

No fault code found.

Address 3B: Sensor Elect. (J849) Labels: 4G0-907-637.clb
Part No SW: 4G0 907 637 B HW: 4G0 907 637 B
Component: SARA 6D H02 0004
Revision: ----- Serial number: EJ1BPA4200K4D.0
Shop #: WSC 00000 000 00000
ASAM Dataset: EV_SARA 006014
ROD: EV_SARA_006.rod
VCID: 2D5B54767C1137EC98-8078

No fault code found.

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 10

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 42: Door Elect, Driver (J386) Labels: 4H0-959-793.clb
Part No SW: 4G8 959 793 C HW: 4G8 959 793 A
Component: TSG FA H04 0210
Revision: ----- Serial number: -----
Coding: 011F46225E00628002080002
Shop #: WSC 02312 785 00200
VCID: 40851DC2D383CA8443-8014

No fault code found.

Address 44: Steering Assist (J500) Labels: 4G0-909-144.clb
Part No SW: 4G0 909 144 L HW: 4G0 909 144 G
Component: RCEPS H38 0010
Revision: 00001000 Serial number: 0009661262
Coding: 101001010000
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_RCEPS 009008
ROD: EV_RCEPS_009.rod
VCID: 3261470A652F6814C5-8066

1 Fault Found:

3158336 - Function Restricted due to Missing Message(s)

U1111 00 [009] - -

[New feature! Extended UDS fault detail is only supported by current gen. interfaces]

Confirmed - Tested Since Memory Clear

Freeze Frame:

Fault Status: 00000001

Fault Priority: 6

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Date: 2023.12.10

Time: 14:12:52

Write only channel

Page 11

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 46: Central Conv. (J393) Labels:. 4H0-907-064-46.clb
Part No SW: 4H0 907 064 AP HW: 4H0 907 064 AP
Component: BCM2 2.0 H24 0217
Revision: 00002001 Serial number: 0146949346
Coding: 01000E2020B9B48083200A840801000000000000000000000000000000000000
Shop #: WSC 02391 785 00200
VCID: 77F7B61EC6CD4D3C32-8022

Subsystem 1 - Part No SW: 4G0 947 135 B HW: 4G0 947 135
Component: Dachelektroni H10 0100
Serial number: 0000000AP00000198755
Coding: 090000

Subsystem 2 - Part No SW: 4G8 959 252 HW: 4G8 959 252
Component: HSP-SG H09 0027
Serial number: WA101142000000248977

No fault code found.

Address 52: Door Elect, Pass. (J387) Labels: 4H0-959-792.clb
Part No SW: 4G8 959 792 C HW: 4G8 959 792 A
Component: TSG BF H04 0210
Revision: ----- Serial number: -----
Coding: 011F46225E00628002080002
Shop #: WSC 02312 785 00200
VCID: 3F871E3EAE7DB57C3A-806A

No fault code found.

Address 53: Parking Brake (----) Labels: 4H0-907-801.clb
Part No SW: 4H0 907 801 E HW: 4H0 907 801 A
Component: EPB-4 H03 0012
Revision: ----- Serial number: 00000000057145
ASAM Dataset: EV_ParkiBrake 001022
ROD: EV_ParkiBrake_VW51.rod
VCID: 2A515F6A4DFF20D47D-807E

No fault code found.

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 12

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 55: Headlight Range (J431) Labels:| 8X0-907-357.clb
Part No SW: 4H0 907 357 A HW: 4H0 907 357 A
Component:LWR12.... H02 0013
Serial number: 110401-0004-015
Coding: 1123A6101002A300
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_HeadlRegulBasic 005001
ROD: EV_HeadlRegulBasic.rod
VCID: 2C5D5972470B3EE48F-8078

No fault code found.

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 13

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 56: Radio (R) Labels: Redir Fail!
Part No SW: 4G0 035 056 J HW: 4G0 035 056
Component: Radio U STD H52 0133
Revision: AB001007 Serial number: 051CN0B7511229
Coding: 010003020100000001
Shop #: WSC 02391 785 00200
VCID: 2855A5625BF312C46B-807C

6 Faults Found:

02983 - Connection between Impedance Converter 1 and Window Antenna

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:13:02

Freeze Frame:

Voltage: 14.80 V

00870 - Bass Speaker Front Left (R21)

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:12:54

Freeze Frame:

Voltage: 14.70 V

00871 - Bass Speaker Front Right (R23)

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:12:54

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 14

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Voltage: 14.70 V

02558 - Rear Left Mid-Range/Woofer Loudspeaker (R159)

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:12:54

Freeze Frame:

Voltage: 14.70 V

02559 - Rear Right Mid-Range/Woofer Loudspeaker (R160)

011 - Open Circuit

Freeze Frame:

Fault Status: 01101011

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:12:54

Freeze Frame:

Voltage: 14.70 V

03029 - Subwoofer (R157)

006 - Short to Plus

Freeze Frame:

Fault Status: 01100110

Fault Priority: 5

Fault Frequency: 1

Reset counter: 91

Mileage: 232788 km

Time Indication: 0

Date: 2023.12.10

Time: 14:12:57

Freeze Frame:

Voltage: 14.70 V

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 15

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 5F: Information Electr. (J794) Labels: 4E0-035-6xx-5F.clb
Part No SW: 4G0 035 666 P HW: 4G0 035 666
Component: H-BN-EU H46 1034
Revision: ----- Serial number: 426C%0B7595636
Coding: 090100040203E1ED45108F3E00000003E00001000000000000
Shop #: WSC 02391 785 00200
VCID: 356B7C169C417F2CE0-8060

Subsystem 1 - Part No: 8R0 060 884 KB
Component: EUR 2022/2023 3501

Subsystem 2 - Part No SW: 4G0 919 605 A HW: 4G0 919 605 A
Component: DU8 C7 SV H42 0021
Serial number: AUZ8ZDB1300HDEI

Subsystem 3 - Part No SW: 4G1 919 610 C HW: 4G1 919 612 L
Component: E380 BDT C7 H08 0204
Serial number: 90349KCV000BL

Subsystem 4 - Part No: 8R0 060 961 A
Component: CD-Database 2712

1 Fault Found:

03157 - Functionality limited due to Communications Disruption

000 - -

Freeze Frame:

Fault Status: 01100000
Fault Priority: 6
Fault Frequency: 1
Reset counter: 91
Mileage: 232788 km
Time Indication: 0
Date: 2023.12.10
Time: 14:13:09

Freeze Frame:

Bin. Bits: 00000000 00000000
Bin. Bits: 00000000 10000000
Bin. Bits: 00000000 00000000
Bin. Bits: 00000000 00000000
Bin. Bits: 00000000 00000000

VCDS
Self-Diagnosis Log
Sunday, 10, December, 2023, 14:22:34:00009
Page 16

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 62: Door, Rear Left (J388) Labels: 4H0-959-795.clb
Part No SW: 4G8 959 795 C HW: 4G8 959 795 A
Component: TSG HL H03 0210
Revision: ----- Serial number: -----
Coding: 010F04224000628002080002
Shop #: WSC 02312 785 00200
VCID: 428117CADD8FD89455-8016

No fault code found.

Address 6D: Trunk Elect. (----) Labels: * Redir Fail!
Part No SW: 4G8 959 107 D HW: 4G8 959 107
Component: HDSG-Modul H12 0036
Revision: 11012001 Serial number: 085100077
Coding: 0A3205C000
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_HDSGAu573 001014
ROD: EV_HDSGAu571.rod
VCID: 36697B1A89477434E9-8062

No fault code found.

Address 72: Door, Rear Right (J389) Labels: 4H0-959-795.clb
Part No SW: 4G8 959 795 C HW: 4G8 959 795 A
Component: TSG HR H03 0210
Revision: ----- Serial number: -----
Coding: 010F04224000628002080002
Shop #: WSC 02312 785 00200
VCID: 428117CADD8FD89455-8016

No fault code found.

Address 8F: Pretens. Frt Left (J854) Labels: 4H0-980-94x-RGS.clb
Part No SW: 4H0 980 945 HW: 4H0 980 945
Component: RGS-VL H05 0070
Coding: 00060000031F030000030801424CDA010000
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_RGS_L 002004
ROD: EV_RGS_L.rod
VCID: 6FE78E7EB69D05FCEA-803A

No fault code found.

VCDS
Self-Diagnosis Log
Sunday,10,December,2023,14:22:34:00009
Page 17

VIN: WAUZZZ4G7BN023481 License Plate: KU9206AF

Address 90: Pretens. Frt Right (J855) Labels: 4H0-980-94x-RGS.clb
Part No SW: 4H0 980 946 HW: 4H0 980 946
Component: RGS-VR H05 0070
Coding: 00060000031F030000030801424CDA010000
Shop #: WSC 02391 785 00200
ASAM Dataset: EV_RGS_R 002004
ROD: EV_RGS_R.rod
VCID: 70E58D02ABA31A04F3-8024

No fault code found.

End------(Elapsed Time: 05:05)-----